



**HEWLETT-PACKARD COMPANY
LOGIC SYSTEMS DIVISION**

**HP 64000
Logic Development
System**

SYSTEM RELEASE BULLETIN

HP STARS II

Issue 87.10

OCTOBER, 1987

This document supersedes all previously dated SSBs.

**HEWLETT
PACKARD**

NOTICE

The information contained in this document is subject to change without notice.

HEWLETT-PACKARD MAKES NO WARRANTY OF ANY KIND WITH REGARD TO THIS MATERIAL, INCLUDING, BUT NOT LIMITED TO, THE IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE. Hewlett-Packard shall not be liable for errors contained herein or for incidental or consequential damages in connection with the furnishing, performance or use of this material.

Hewlett-Packard assumes no responsibility for the use or reliability of its software on equipment that is not furnished by Hewlett-Packard.

This document contains proprietary information which is protected by copyright. All rights are reserved. No part of this document may be photocopied, reproduced or translated to another language without the prior written consent of Hewlett-Packard Company.

READER COMMENT SHEET

STARS II SRB (STARS B)

Issue _____ DATE ____/____/____

We welcome your evaluation of this bulletin. Your comments and suggestions help us to improve our publications. Please use additional pages if necessary.

Is this bulletin technically accurate? Yes [] No [] (If no, explain under Comments, below.)

Are the concepts and wording easy to understand? Yes [] No [] (If no, explain under Comments, below.)

Is the format of this bulletin convenient in size, arrangement and readability? Yes [] No [] (If no, explain or suggest improvements under Comments, below.)

Comments:

Date: _____

FROM:

Name _____


Company _____

Address _____

STARS B
Printed in U.S.A.

FOLD

FOLD



NO POSTAGE
NECESSARY
IF MAILED
IN THE
UNITED STATES



BUSINESS REPLY MAIL

FIRST CLASS PERMIT NO. 1303 COLORADO SPRINGS, CO.

POSTAGE WILL BE PAID BY ADDRESSEE

STARS Administration
Hewlett-Packard Company
Logic Systems Division
P.O. BOX 617
Colorado Springs, Colorado 80901-0617

FOLD

FOLD

P R E F A C E

This Software Release Bulletin documents all fixes and enhancements that are incorporated in the new release identified on the cover page. The SRB is provided as a benefit of Hewlett-Packard's Account Management Support, Response Center Support, and Software Materials Subscription.

Of the five sections contained in the SRB (not including the PREFACE), only the last section which contains the detailed reports has page numbers. These are referenced by the product, report number and keyword indexes in order to direct the user to a particular area or to an individual detailed report. The five sections are described below.

SOFTWARE RELEASE CONTENTS

This section lists the product names, numbers and update/fix levels of all products contained in this release. Products that have changed, or are new are denoted with an asterisk preceding the product name.

PRODUCT INDEX

Each unique product name/number has an entry listing the page number where the detailed report for that product begins.

REPORT NUMBER INDEX

This index is a sequential list of the individual report numbers with the corresponding page number where the report can be found.

KEYWORD INDEX

This index is sorted by product name, keyword, product number (including the update/fix level) and by report number in that order. In addition to the sort items, each entry has a brief description (one line) and the page number where the detailed report can be found. Note that a given report can be listed more than once in this section if it has more than one keyword assigned to it.

DETAILED REPORTS

Each report contains all the available information relevant to the problem being corrected or the enhancement being implemented.

Software release contents

Product name	Product number	uu.ff
*6301V/03R EMUL	64206	01.01
*64180 EMUL	64180	01.01
*68000 DQ EMUL	300 64243S004	01.10
*68008 EMULATION	300 64244S004	01.10
*68010 EMUL 12.5M	300 64245S004	01.10
*70108 EMUL	64295	01.00
*70116 EMUL	64294	01.00
*70208 EMUL	64297S004	01.00
*70216 EMUL	64296S004	01.00
*8085 EMULATION	300 64203S004	01.10
*HOST SOFTWARE / VAX	64882	02.10
*OPERATING SYSTEM	64100	02.09
*SOFTKEY EDITOR	300 64790S004	02.00
*SOFTKEY EDITOR	500 64790S001	02.00
*USER DEF ASSEMB	300 64851S004	01.30
*USER DEF ASSEMB	500 64851S001	01.70
*USER DEF ASSEMB	VAX 64851S003	01.70
*USER INTERFACE	300 64808S004	02.00
*USER INTERFACE	500 64808S001	02.00

Product index

Product name		Product number	Page
68000 DQ EMUL	300	64243S004	1
68008 EMULATION	300	64244S004	2

Report number index

Report #	page	Report #	page	Report #	page	Report #	page
D200078063	2	D200078121	1	D200078139	2		

Keyword index

- -8

Keyword	Product number	uu.ff Description	Report #	page
*****none*****	64243S004	01.00 Loading target memory is too slow.	D200078121	1
Keyword	Product number	uu.ff Description	Report #	page
*****none*****	64244S004	01.00 Ehalt occurring too often while running user code.	D200078063	2
	64244S004	01.00 Loading target memory is too slow.	D200078139	2

SRB detail reports as of 08/20/87

Page: 1

Number: D200078121 Product: 68000 DQ EMUL 300 64243S004 01.00

One-line description:

Loading target memory is too slow.

Signed off 08/20/87 in release 401.10

SRB detail reports as of 08/20/87

Page: 2

Number: D200078063 Product: 68008 EMULATION 300 64244S004 01.00

One-line description:

Ehalt occurring too often while running user code.

Signed off 08/20/87 in release 401.10

Number: D200078139 Product: 68008 EMULATION 300 64244S004 01.00

One-line description:

Loading target memory is too slow.

Signed off 08/20/87 in release 401.10



5958-6019, Sept. 1987
E0987

Printed in U.S.A.